

## **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 21-Nov-14 **Time** 12:43 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

**Suspension Bridge** 

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 127 Const Calendar Day: 622 Date: 23-May-2011 Monday Inspector Name: Khow, Sanny Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 17:30 PM Break: 00:30 Over Time: 02:00

Federal ID: Location:

Reviewer: Soheilifard, Saman Approved Date: 25-Jul-11 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM Precipitation Condition

Working Day **V** If no, explain:

04-0120F4 Bid Item: 053 T-L01-SFN.053 Tower Lift 01 Strut Façades North Erect structural steel (bridge tower)

AMERICAN BRIDGE/FLUOR, A JV

04-0120F4 Bid Item: 053 T-L01-TNE.053 Tower Lift 01 Tower NE Erect structural steel (bridge tower)

AMERICAN BRIDGE/FLUOR, A JV

04-0120F4 Bid Item: 053 T-L04-BNW.053 Tower Lift 04 Bolt Tower NW

AMERICAN BRIDGE/FLUOR, A JV

Labor								
Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor:	AMERICAN BRIDGE/F	LUOR, A JV						
Ironworker	APP	LUIS PLANCARTE	8.00	2.00	0.00	10.00	1	
Ironworker	APP	Lorenzo Padilla	8.00	2.00	0.00	10.00	1	
Ironworker	JNM	EDUARDO JIMENEZ-PADILLA	8.00	2.00	0.00	10.00	1	
Ironworker	JNM	Wei Tan	8.00	2.00	0.00	10.00	1	
Ironworker	JNM	MATTHEW GREER	8.00	2.00	0.00	10.00	1	
Ironworker	FOR	Kevin Karnar	8.00	2.00	0.00	10.00		

Diary: Dispute

General Comments 053 T-L04-BNW.053

Final Bolt Field Splice 3

North Shaft

Torque verification for the M27 A490 bolts are completed at the following locations:

Longitudinal stiffener at Splice 3 - North Shaft

Upper and lower Splice:

Skin A – Longitudinal stiffeners A1, A2, A3 and A4

Skin B - Longitudinal stiffeners B1

Skin C – Longitudinal stiffeners C1, C2

Skin D - Longitudinal stiffeners D2, D3, D4

Skin E – Longitudinal stiffeners E1, E2



Page 1 of 2

## Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Khow, Sanny Diary #: 127 Date: 23-May-2011 Monday

Torque verification for the M27 A490 bolts are completed at the following locations: All skin splice plate interior bolts (bolts that are turned from the nut side) - North Shaft 04-0120F4 Bid Item: 078 T-L02-ISW.078 **Tower Lift 02 Internal Paint Tower SW** CERTIFIED COATINGS COMPANY Labor Trade Class Name RT Hrs OT Hrs DT Hrs Total Remarks Dispute Contractor: CERTIFIED COATINGS COMPANY MIKE GAYA Painter FOR 0.00 0.00 0.00 0.00 FOR Painter TONY KATRONES 0.00 0.00 0.00 0.00 04-0120F4 Bid Item: 078 T-L02-ISW.078 **Tower Lift 02 Internal Paint Tower SW** AMERICAN BRIDGE/FLUOR, A JV